



Remove the back, top, forehead and bottom jaw and set aside.



Place the 3 1x2 red downlight plates where indicated. You will need to replace the existing trans red 1x2 plate.




Feed the wires through the gaps into the back of the skull.




Reattach the jaw.




Put the bare white leds into position passing the wire between the studs of the hinge piece.



Feed the wires through the same gaps as earlier and reattach the forehead.



Join up any 2 wires using
the Y connector



Place battery pack inside the skull
and put back all remaining pieces.



DIY GUIDE TO LIGHTING Carnage

