



Parts you will need.

1 x AAA Battery box with 4 leads

1 x Y connector

2 x Green 1x2 downlights

2 x White bare LED

1 x Green bare LED

Remove the back of Venoms head




Remove his forehead, eyes and jaw as shown







Remove teeth and gums




Put the bare green LED into place as shown.
I have used a tiny amount of bluetack to hold the wire in place while I took a photo. This is not normally required but it also made it easier to put everything back in place.

Replace gums and feed wire through the gaps






Place the 2 sets of 1x2 green plates as shown




Feed the wires though the gaps




Reattach the jaws

Reattach his eyes and feed through the white LEDs




Reattach his brow





Position the LEDs as shown the put his eyebrows back on.
As said before bluetack is not required but makes it easier.



Connect the wires to the battery box

Put the battery pack in his head and turn on

