Lego 75354


Darth Vadar Helmet Installation Guide








First of all, separate the base to modify it by the 1x2 plates provided




Split the base as shown, detach the 1x8s and 1x10s on the side



Rearrange the base by putting the 1x8's at the bottom with one 1x2 plate on each side, the cover the top by the remain 1x2 and the 1x10



Then assemble the 1x2 and 1x10 plates on the base




Restore the base, then detach the top of the helmet




Assemble the spot lights on the expanded corners of the base, then move the remain lights to the top of the helmet




The cable from the spot light to lighting plate could be stabilized at the shown area Remove the shown parts, put the cable in between then put it back



Assemble the lighting plate



Then move the connect to the back




Now you can restore the helmet



To power up by the USB cable, just simply connect it with the connector



To power by battery, remove the back part from the helmet and stick the battery case as shown





*Beware, if you powered by power bank with protection it might be turned off by itself due to the power consume is too little, then you need to power by AC adaptor or use the battery