

Installation Guide







First of all, detach the shown parts from the helmet




Take the red parts from the previous step and move them on the lighting parts



To assemble the lighting parts, start from the 1x4 lighting plates to the shown spot



Remove the shown parts to put the eyes on the mask easier then move the connector through the gap to the area on top of the head



Restore the removed parts and there should be no wire can be seen at the front




To power the lights by USB, connect the connector with the USB cable



Use the parts from the previous step to stable the wire



To power by battery, you can just connect the battery case and put it inside the helmet



*Beware, if you powered by power bank with protection it might be turned off by itself due to the power consume is too little, then you need to power by AC adaptor or use the battery