

Remove top of display case and turn over.

Remove the 6 screws and the grey lid will come off.

Place the 4 LED strips evenly around the lid pressing down FIRMLY for at least 5 seconds to ensure the adhesive has time to bond.

Poke a hole through the rubbery cover so that the plug can pass through.

Wrap the wire around the two little posts to help prevent accidental pulling of the LED strips.

Put the clear part back onto the lid and put the screws back in.

Plug it in and add power and you are done.



