

Lego 76165 IRON MAN Helmet

Installation Guide









First of all, split the helmet as shown



Start assembling from the 1x4 lighting plate at the chin area




Then stick the led bulbs on the forehead area as shown, to make the lights face the eyes




Now restore the face back to the helmet, make sure the wires are not on any studs







Restore the whole face and place the wire at the middle




Then remove the back parts of the helmet and pull the wire to the back



To power by USB, connect the cable then stabilize the wire at the back by the removed parts




At last, restore the top of the helmet then you can light it on



*Beware, if you powered by power bank with protection it might be turned off by itself due to the power consume is too little, then you need to power by AC adaptor or use the battery

If powered by battery, the battery case can be placed inside the helmet Connect the cable with the case then put it inside the helmet



Then restore the back of the helmet Turn on battery case and put the top back on it

